



- ☒ Partial
☐ Complete
☐ Exploration

0001

Inspection Date: 1/27/99
Time: 2:00 ☐ am ☒ pm to 5:30 ☐ am ☒ pm
Date of Last Inspection: 12/15/99

Mine Name: Hidden Valley County: Carbon Permit Number: Act 015/007

Permittee and/or Operator's Name: Consolidated Coal Company

Business Address: P.O. Box 566, Sessou, Illinois

Type of Mining Activity: ☒ Underground ☐ Surface ☐ Prep. Plant ☐ Other

State Official(s): Bill Malenchuk

Company Official(s): N/A

Federal Official(s): N/A

Weather Conditions: Pt Cloudy - Temp 40°

Existing Acreage: Permitted- 950 Disturbed- 7 Regraded- Seeded- Bonded- 7

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: ☐ Exploration / ☐ Active / ☒ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture

☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability 1986 Year)

A Seam Reclaimed 1997

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 015/007

Inspection Date 1/27/99

Please number comments to correspond with topics on previous page.

General Comments Mr. Behling phone me on 1/23/99 and advised me that he had just completed an inspection of the Hidden Valley Reclaimed mine.

I conducted an inspection on 1/27/99 and Mr. Behling advised me he would be in Salt Lake that day.

Drainage and Water Bars The work performed by the permittee last year on the reclaimed road water bars et al and the diversion above the A seam were observed and no problems noted.

Revegetation The regrading and seeding of the B seam outslope in 1997 was observed. The depressions are not filling up with sediment. However, the depressions are establishing a micro climate that is more conducive to storing moisture and some shading to protect plant seedlings.

The work done in 1998 mentioned herein was also done with due care to scarify the surface, prepare a seed bed and seeding the redisturbed area.

Copy of report mailed to CCC/Tim Kochbaum, OSM/Henry Austin, DOSM/Doc Helfrich

Copy of report given to Local Field Office

Inspector's signature Jim J. Maloney

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE